

---

---

Current Version	1.13	(previous version 1.12)
Date Code	02/27/2004 15:49	
Checksum	0x2AFA	

New Changs:

- 1) New cpu modules from Tyan BIOS codebase
- 2) Change BBS configuration from 2 to 0.
- 3) Enable spread spectrum.
- 4) Prefetch Flush Enable bit. PCI32 slot unstable issue.
- 5) Add Intel CPU 0F25H ucode M01F2514
- 6) Xeon L3 cache DMI info size=400

Tested items(Bugs fixed):

- 1)If Lan card - Intel PRO/1000 MT server (GbE) plug in PCI solt 5 then run radia test the result is fail in TurboLinux Server 8. (Bug ID 055)

<Root Cause>

Per the ICH EDS, page 314, Device 30 (0x1e) Function 0,Register Offset 50-53, bit 13 is the Prefetch Flush Enable bit.

Per the document this bit should be set by default. For proper cache coherency this bit must be set to 1 by the BIOS

<Solution>

BIOS add code to enable this bit

<Verification>

- 1)Intel PRO/1000 MT server (GbE) plug in PCI solt 5
- 2)Setup TurboLinux Server 8.
- 3)Follow Radia test procedure.

Tested items(Bugs fixed):

- 2)If Lan card - 3Com 3C996B-T (GbE) plug in PCI solt 5 then run radia test the result is fail in SCO OpenServer 5.0.7 (Bug ID 057)

<Root Cause>

Per the ICH EDS, page 314, Device 30 (0x1e) Function 0,Register Offset 50-53, bit 13 is the Prefetch Flush Enable bit.

Per the document this bit should be set by default. For proper cache coherency this bit must be set to 1 by the BIOS

<Solution>

BIOS add code to enable this bit

<Verification>

- 1)Lan card - 3Com 3C996B-T (GbE) plug in PCI slot 5
- 2)Setup TurboLinux Server 8.
- 3)Follow Radia test procedure.

Tested items(Bugs fixed):

3)Plug 3Com 3C996B-T NIC in PCI slot 3 & 5 and install Windows SBS 2000 as configuration listed, then run Radia. The client which connected to 3COM LAN card in slot 5 will occur error "TEST COMPLETE ERROR FOUND, Compare error" or "TEST STOP, I/O ERROR (COPY):> 30 redirect" in the client.  
(Bug ID 071)

<Root Cause>

Per the ICH EDS, page 314, Device 30 (0x1e) Function 0, Register Offset 50-53, bit 13 is the Prefetch Flush Enable bit. Per the document this bit should be set by default. For proper cache coherency this bit must be set to 1 by the BIOS

<Solution>

BIOS add code to enable this bit

<Verification>

- 1)Lan card - 3Com 3C996B-T (GbE) plug in PCI slot 5
- 2)Setup Windows2000 sbs.
- 3)Follow Radia test procedure.

Tested items(Bugs fixed):

4)Sometime the LAN boot order is prior to the hard drive and user didn't change the BIOS default boot order.  
(Bug ID 074)

<Root Cause>

AMI BBS mode 2 spec do not meet HP's requirement. HP prefer mode 0.

<Solution>

Disable the AMI enhanced BBS function. BIOS will restore the previous boot order if the hard disk attached.

<Verification>

- 1)Plug in hard drive and make sure hard drive's priority is higher than the lan's priority.
- 2) Plug out hard drive and reboot system and into BIOS setup utility. Priority will be floppy, cdrom, lan.
- 3) Plug in hard drive and reboot system and into BIOS setup utility. Priority will be floppy, cdrom, hard drive, lan.