read me first

hp StorageWorks fca2355 dual channel PCI host bus adapter

This document describes known issues with the FCA2355 dual channel PCI host bus adapter.

Windows NT

The following problem occur when running Windows NT with Secure Path V4.0 for Windows:

When viewing Secure Path port entries for the FCA2355DC HBA, the slot number appears as **255** for one port and a dash (-) for the other port. This is a problem with a driver that is not Secure Path-related. It will be corrected in a future release.

Documentation Corrections

FCA2355 Dual Channel PCI Host Bus Adapter Installation Guide Correction

On page 5-10 in the Drive Parameters table, the correct values for **Topology=n** are as follows:

 $\ensuremath{\mathbb{C}}$ Hewlett-Packard Company, 2002. All rights reserved.

Printed in the U.S.A.

AV-RU0XA-TE November 2002

All other product names mentioned herein may be trademarks of their respective companies. The information in this document is subject to change without notice. Value 0 through 3. Default = 2.

0 = FC_AL (loop), 1 = PT-PT Fabric, 2=FC-AL first, then attempt PT-PT, 3=PT-PT first, then attempt FC-AL. When set to 1, FLOGI, SCR/RSCN and NameServer queries are employed.

FCA2355 Dual Channel PCI Host Bus Adapter Release Notes Correction

On page 6, the product configurations supported by the FCA2355 HBA are as follows.

Product	Secure Path Product Versions
Array Controller Software (ACS) V8.6 and V8.7 for HSG 80	Windows V4.0
Enterprise Virtual Array V2.0	Windows V4.0
MSA1000 V.1	Windows V4.0
	Windows Workgroup Edition V4.0