

MSA500 version 1.80

This MSA500 firmware will recommend updates for some SCSI disk drive models after the MSA500 firmware has been installed. To avoid notification on the LCD panel, update any applicable hard disk drives before updating the MSA500 firmware.

Disk drive firmware components are available from:

http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99_56.html

If a component is not available for the affected disk drive model, download the following ROMPaq:

<http://h18000.www1.hp.com/support/files/server/us/download/17149.html>

A later version of the disk drive firmware may be available and should be used.

Disk Drive Model	Minimum Firmware	Disk Drive Family
BB009235B6	B021	SCSI 9GB 7200 WU2
BB018135B5	B021	SCSI 18GB 7200 WU2
BB018235B7	B021	SCSI 18GB 7200 WU2
BD009635C3	B022	SCSI 9GB 10K WU3
BD009735C6	B022	SCSI 9GB 10K WU3
BD018635C4	B022	SCSI 18GB 10K WU3
BD0186459A	B011	SCSI 18GB 10K WU3
BD018735C7	B022	SCSI 18GB 10K WU3
BD018745A3	B011	SCSI 18GB 10K WU3
BD036635C5	B022	SCSI 36GB 10K WU3
BD0366459B	B011	SCSI 36GB 10K WU3
BD036735C8	B022	SCSI 36GB 10K WU3
BD036745A4	B011	SCSI 36GB 10K WU3
BD0726459C	B011	SCSI 72GB 10K WU3
BF01865222	B009	SCSI 18GB 15K WU3
BF03665223	B009	SCSI 36GB 15K WU3