# CPD-E100, HMD-A100, A200 – Information data on OSD will be changed by DAS

Issue: The Information data on OSD for X11R chassis will be changed by DAS communication.

Problem/Description: When the monitor communicate to the PC (DASJC1.3) for alignment,
The Information data on OSD will be changed as following pictures.

<Before DAS communication>   <After communication by DAS>

Cause: The cause of this symptom, we are still under investigating.

Solution: After all alignment by DAS, Select "Step-by-Step" from Adjustments menu, then select "Completion of Alignment".

Completion of Alignment

Operate this step completely, then check the Information data on OSD.