

**HP/NHP SATA 3.5" Hard Drive Compatibility Table**

Option Kits (Spare Kit)	Systems																				Supported Drive Models													
	Capacity (GB unless otherwise noted)	ProLiant ML380 G5	ProLiant ML350 G4p	ProLiant ML310 G5	ProLiant ML310 G4	ProLiant ML310 G3	ProLiant ML310 G2	ProLiant ML150 G5	ProLiant ML150 G3	ProLiant ML150 G2	ProLiant ML115 G5	ProLiant ML115 G3	ProLiant ML110 G5	ProLiant ML110 G2/G3/G4	ProLiant DL380 G4p	ProLiant DL360 G4	ProLiant DL320 G5p	ProLiant DL320 G4/G5	ProLiant DL320 G3	ProLiant DL320s		ProLiant DL185 G5	ProLiant DL180 G5	ProLiant DL180 G1 (AP.J only)	ProLiant DL165 G5	ProLiant DL160 G5	ProLiant DL145 G3	ProLiant DL145 G2	ProLiant DL140 G3	ProLiant DL140 G2	ProLiant DL120 G5	StorageWorks MSA60	StorageWorks MSA20	
<b>Previous Generation</b>																																		
383410-B21+ (399967-001)	80					X					X		X					X						X	X	X	X	X	X					6L080M0, ST3808110AS, FB080C4080, WD800AAJS-70TDA1
411275-B21+ (399968-001)	160					X	X				X	X	X	X				X						X	X	X	X	X	X	X				6L160M0, ST3160812AS, FB160C4081, WD1600JS-70SGB1, GB0160CAABV
411276-B21+ (399969-001)	250					X	X				X	X	X	X				X						X	X	X	X	X	X	X				7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250C8045
*404469-B21+ (404654-001) (404654-002)	500					X	X				X	X	X	X				X						X	X	X	X	X	X	X				6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1
349237-B21 (397551-001)	80	X	X	X	X	X	X		X	X					X	X	X	X	X	X	X	X	X	X	X	X	X	X	X					6L080M0, ST3808110AS, FB080C4080, WD800AAJS-70TDA1
349238-B21 (397552-001)	160	X	X	X	X	X	X		X	X					X	X	X	X	X	X	X	X	X	X	X	X	X	X	X					6L160M0, ST3160812AS, FB160C4081, WD1600JS-70SGB1, GB0160CAABV
349239-B21 (397553-001)	250	X	1, 2	X	X	2	X	X	X	X					X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X		7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250C8045
395473-B21 (395501-001) (395501-002)	500	X	1, 2	X	X	2	X	X	X	X					X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X		6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1
432341-B21 (432401-001) (432401-002)	750	X	1, 2	X	X	2	X	X							X		X	X	X	X	X	X	X	X	X	X	X	X		X	X		ST3750640NS, GB0750C4414, BF0750C8047	
<b>Current Generation</b>																																		
458947-B21+ (483096-001) 3.0Gb	160					X				X	X													X	3					X			GB0160EAFJE	
458939-B21+ (459315-001) 3.0Gb	250					X				X	X													X	3					X			GB0250EAFJF	
458941-B21+ (459316-001) 3.0Gb	500					X				X	X													X	3					X			GB0500EAFJH	
462595-B21+ (462618-001) 3.0Gb	750					X				X	X													X	3					X			GB0750EAFJK	
458945-B21 (483095-001) 3.0Gb	160	X		3	3	X	3									3	3			X	3	3	X	3									GB0160EAFJE	
458926-B21 (459318-001) 3.0Gb	250	X		3	3	X	3									3	3			X	3	3	X	3					X	X			GB0250EAFJF	
458928-B21 (459319-001) 3.0Gb	500	X		3	3	X	3									3	3			X	3	3	X	3					X	X			GB0500EAFJH	
458930-B21 (459320-001) 3.0Gb	750	X		3	3	X	3									3	3			X	3	3	X	3					X	X			GB0750EAFJK	
454146-B21 (454273-001) 3.0Gb	1 TB	X		3	3	X	3									3	3			X	X	3	3	X	3				X	X			GB1000EAFJL	

Contain 7200 RPM drives  
+ Denotes Non Hot Plug  
\* Denotes FIO only

\* Compatibility Notes:  
Blank= Not Supported  
X= Supported

1= To ensure optimum thermal conditions, the server should be running with the 8-19-05 system ROM or later.  
2= When running 3 or more drives in this server, it is recommended that the system configuration be set for 100% fan speed.  
3= A minimum version of System ROM is required to support this 3G SATA drive on this server when configured with an embedded SATA controller.

© Copyright 2004-2008 Hewlett-Packard Development Company, L.P.  
The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

July 2008