

HP/NHP SATA 3.5" Hard Drive Compatibility Table

Optional Kits (Spare Kit)	Capacity (GB unless otherwise noted)	Systems																				Supported Drive Models												
		ProLiant ML 350 G5	ProLiant ML 350 G4p	ProLiant ML 310 G5	ProLiant ML 310 G4	ProLiant ML 310 G3	ProLiant ML 310 G2	ProLiant ML 190 G5	ProLiant ML 190 G3	ProLiant ML 190 G2	ProLiant ML 115 G5	ProLiant ML 115	ProLiant ML 110 G5	ProLiant ML 110 G2/G3/G4	ProLiant DL 360 G4p	ProLiant DL 360 G4	ProLiant DL 320 G5p	ProLiant DL 320 G4G5	ProLiant DL 320 G3	ProLiant DL 320s	ProLiant DL 185 G5		ProLiant DL 180 G5	ProLiant DL 180 G1 (APJ only)	ProLiant DL 165 G5	ProLiant DL 160 G5	ProLiant DL 145 G3	ProLiant DL 145 G2	ProLiant DL 140 G3	ProLiant DL 140 G2	ProLiant DL 120 G5	StorageWorks MSA60	StorageWorks MSA20	
383410-B21+ (399967-001)	80					X					X		X					X								X	X	X	X	X				6L080M0, ST3808110AS, FB080C4080
411275-B21+ (399968-001)	160					X	X			X	X	X	X					X							X	X	X	X	X	X			6L160M0, ST3160812AS, FB160C4080, WD1600JS-70SGB1, GB0160CAABV	
458947-B21+	160																																GB0160EAFJE	
3.0Gb (sps 483096-001)																																		
411276-B21+ (399969-001)	250					X	X			X	X	X	X					X							X	X	X	X	X	X	X		7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250C8045	
458939-B21+	250																																GB0250EAFJF	
3.0Gb (sps 459315-001)																																		
*404469-B21+ (404654-001)	500					X	X			X	X	X	X					X							X	X	X	X	X	X	X		6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1, WD5000YS-70MPB1, BF0500C8046	
(404654-002)																																		GB0500EAFJH
458941-B21+	500																																	
3.0Gb (sps 459316-001)																																		
462695-B21+	750																																	GB0750EAFJK
3.0Gb (sps 462618-001)																																		
349237-B21 (397551-001)	80	X	X	X	X	X	X			X	X				X	X	X	X	X	X	X	X	X				X		X				6L080M0, ST3808110AS, FB080C4080	
349238-B21 (397552-001)	160	X	X	X	X	X	X	X	X						X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X			6L160M0, ST3160812AS, FB160C4080, WD1600JS-70SGB1, GB0160CAABV	
458945-B21	160																																	GB0160EAFJE
3.0Gb (sps 483095-001)																																		
349238-B21, 411275-B21	160																																	WD1600JS-70SGB1, GB0160CAABV
349239-B21 (397553-001)	250	X	1, 2	X	X	2	X	X	X	X					X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250C8045	
458926-B21	250																																	GB0250EAFJF
3.0Gb (sps 459318-001)																																		
349239-B21, 411276-B21	250																																	WD2500YS-70SHB1, GB0250C8045
395473-B21 (395501-001)	500	X	1, 2	X	X	2	X	X	X	X					X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1, WD5000YS-70MPB1, BF0500C8046	
(395501-002)																																		GB0500EAFJH
458928-B21	500																																	
3.0Gb (sps 459319-001)																																		
395473-B21, 411276-B21	500																																	WD5000YS-70MPB1, BF0500C8046
432341-B21	750																																	BF0750C8047
432341-B21 (432401-001)	750	X	1, 2	X	X	2		X	X						X		X		X	X	X	X	X	X	X	X	X	X		X	X		ST3750640NS, GB0750C4414, BF0750C8047	
(432401-002)																																		
458930-B21	750																																	GB0750EAFJK
3.0Gb (sps 459320-001)																																		
454146-B21	1 TB																																	GB1000EAFJL
3.0Gb (sps 454273-001)																																		

Contain 7200 RPM drives  
+ Denotes Non Hot Plug  
\* Denotes FIO only  
\* Compatibility Notes:  
Blank= Not Supported  
X= Supported  
1= To ensure optimum thermal conditions, the server should be running with the 8-19-05 system ROM or later.  
2= When running 3 or more drives in this server, it is recommended that the system configuration be set for 100% fan speed.

© Copyright 2004 Hewlett-Packard Development Company, L.P.  
The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.