

HP/NHP SATA 3.5" Hard Drive Compatibility Table

Option Kits (Spare Kit)	Systems																												Supported Drive Models							
	Capacity (GB unless otherwise noted)	ProLiant ML 350 G5	ProLiant ML350 G4p	ProLiant ML 310 G5	ProLiant ML310 G4	ProLiant ML310 G3	ProLiant ML310 G2	ProLiant ML 150 G5	ProLiant ML 150 G3	ProLiant ML 150 G2	ProLiant ML 115 G5	ProLiant ML 115	ProLiant ML 110 G5	ProLiant ML110 G4	ProLiant ML110 G2/G3	ProLiant DL360 G4p	ProLiant DL360 G4	ProLiant DL320 G5p	ProLiant DL320 G4/G5	ProLiant DL320 G3	ProLiant DL320s	ProLiant DL185 G5	ProLiant DL180 G5	ProLiant DL180 G1 (APJ only)	ProLiant DL165 G5	ProLiant DL160 G5p	ProLiant DL160 G5	ProLiant DL145 G3		ProLiant DL145 G2	ProLiant DL140 G3	ProLiant DL140 G2	ProLiant DL120 G5	StorageWorks MSA60	StorageWorks MSA20	
Previous Generation	Internal Drive Models																												Supported Drive Models							
383410-B21+ (399967-001)	80					X					X		X	X						X						X		X	X	X	X	X				6L080M0, ST3808110AS, FB080C4080, WD800AAJS-70TDA1
411275-B21+ (399968-001)	160					X	X				X	X	X	X	X					X						X		X	X	X	X	X	X			6L160M0, ST3160812AS, FB160C4081, WD1600JS-70SGB1, GB0160CAABV
411276-B21+ (399969-001)	250					X	X				X	X	X	X	X					X						X		X	X	X	X	X	X			7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250C8045
*404469-B21+ (404654-001) (404654-002)	500					X	X				X	X	X	X	X					X						X		X	X	X	X	X	X			6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1
349237-B21 (397551-001)	80	X	X	X	X	X		X	X							X	X	X	X	X	X	X	X	X	X	X	X		X	X					6L080M0, ST3808110AS, FB080C4080, WD800AAJS-70TDA1	
349238-B21 (397552-001)	160	X	X	X	X	X	X	X	X							X	X	X	X	X	X	X	X	X	X	X	X		X	X					6L160M0, ST3160812AS, FB160C4081, WD1600JS-70SGB1, GB0160CAABV	
349239-B21 (397553-001)	250	X	1, 2	X	X	2	X	X	X	X						X	X	X	X	X	X	X	X	X	X	X		X	X			X	X	7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250C8045		
395473-B21 (395501-001) (395501-002)	500	X	1, 2	X	X	2	X	X	X	X						X	X	X	X	X	X	X	X	X	X		X	X			X	X	X	6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1		
432341-B21 (432401-001) (432401-002)	750	X	1, 2	X	X	2	X	X							X		X	X		X	X	X	X	X	X		X	X			X	X	X	ST3750640NS, GB0750C4414, BF0750C8047		
Current Generation																																				
458947-B21+ (483096-001) 3.0Gb	160					X					X	X	X	X												X	X	3	X		X			GB0160EAFJE, GB0160EAEZH		
458939-B21+ (459315-001) 3.0Gb	250					X					X	X	X	X												X	X	3	X		X		X		GB0250EAFJF	
458941-B21+ (459316-001) 3.0Gb	500					X					X	X	X	X												X	X	3	X		X		X		GB0500EAFJH	
462595-B21+ (462618-001) 3.0Gb	750					X					X	X	X	X												X	X	3	X		X		X		GB0750EAFJK	
458945-B21 (483095-001) 3.0Gb	160	X	X	3	3		X	3											3	3		X	X	3	3	X	X	3	X		X				GB0160EAFJE, GB0160EAEZH	
458926-B21 (459318-001) 3.0Gb	250	X	1, 2	3	3		X	3											3	3		X	X	3	3	X	X	3	X		X		X	X	GB0250EAFJF	
458928-B21 (459319-001) 3.0Gb	500	X	1, 2	3	3		X	3											3	3		X	X	3	3	X	X	3	X		X		X	X	GB0500EAFJH	
458930-B21 (459320-001) 3.0Gb	750	X	1, 2	3	3		X	3											3	3		X	X	3	3	X	X	3	X		X		X	X	GB0750EAFJK	
454146-B21 (454273-001) 3.0Gb	1 TB	X	1, 2	3	3		X	3											3	3		X	X	3	3	X	X	3	X		X		X	X	GB1000EAFJL	

Contain 7200 RPM drives
+ Denotes Non Hot Plug
* Denotes FIO only

* Compatibility Notes:
Blank= Not Supported
X= Supported

1= To ensure optimum thermal conditions, the server should be running with the 8-19-05 system ROM or later.
2= When running 3 or more drives in this server, it is recommended that the system configuration be set for 100% fan speed.
3= A minimum version of System ROM is required to support this SATA drive on this server when configured with an embedded SATA or embedded SATA RAID controllers.

© Copyright 2004-2008 Hewlett-Packard Development Company, L.P.
The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.