ProLiant Parallel Database Cluster for Red Hat Linux Sample Configuration

2 DL580, EVA5000

- 2 X DL580 G2 each w/ 2 2.0 GHz CPUs & 4 GB Memory
- Dual path GigE interconnect
- Dual path FC configuration
- 1 X EVA5000 with 84 X 36.4 GB Drives, external FC switches

This document specifies the basic building blocks necessary for implementing a Parallel Database Cluster solution for Oracle RAC. This list is not intended to be a comprehensive proposal. It is simply an example of the basic server and storage components required. Contact an authorized reseller for a more detailed proposal.

Detailed Bill Of Materials (BOM)

| Quantity | Part Number | Description | |
|----------------------|-------------|---|--|
| Servers: DL580G2 | | | |
| 2 | 202176-001 | ProLiant DL580R02 x2.0-2MB, 2048 MB (2P) | |
| 2 | 202171-B21 | 2048MB PC1600 Registered ECC SDRAM Memory Kit (4 x 512MB) | |
| 8 | 286713-B22 | 36.4 GB 10,000 rpm U320 Universal Hard Drive (1") | |
| 2 | 401782-002 | 3 Years, 7X24, 4hr Response (System) | |
| StorageWorks EVA5000 | | | |
| 84 | 238590-B23 | 36.4 GB 10,000 rpm 2 Gb FC-AL Hard Drive (1") | |
| 1 | 283198-B23 | Enterprise 2C6D-C | |
| 1 | 250203-B27 | VCS Media Kit V3.0b Dual HSV 110 Controller software | |
| 1 | 189715-003 | Storage Management Appliance III | |
| 2 | 221691-B22 | LC-SC 5 Meter Fibre Channel cables (for the Storage Management Appliance) | |
| 1 | 263474-B22 | IP CT5 cable 6FT 8PK All (Connections: between RILOE and Appliance and from Switch to Server) | |
| 1 | 258158-888 | Configure to Order (CTO) | |
| Storage Interconnect | | | |
| 2 | 322120-B21 | StorageWorks SAN Switch 2/8-EL | |

Page 1 of 2

| Quantity | Part Number | Description | |
|----------------------|--------------------|---|--|
| 4 | 281541-B21 | Fibre Channel Host Adapter Kit PCI (FCA2214) | |
| 1 | | Enterprise OS Solution Kit Linux v3.0 - downloadable | |
| 4 | 221692-B22 | 5 Meter FC LC-LC Multi-Mode cable | |
| Cluster Interconnect | | | |
| 2 | J4898A | hp Procurve 2708 Gigabit Ethernet Switch | |
| 6 | 244948-B21 | NC7770 PCI-X gigE Adapters | |
| Rack Parts | S | | |
| 1 | 245163-B21 | Compaq Rack Model 10622 (22U height) | |
| 1 | 252663-D71 | Power Distribution Unit - Low Voltage 24A | |
| Software Components | | | |
| 1 | 308225-B22 | PDC for Linux Cluster Kit | |
| 2 | 282412-B22 | Secure Path v3.0A for Linux | |
| 2 | Red Hat Linux | Red Hat Linux Enterprise Linux 2.1 AS Software and Licenses | |
| | | Temporary licensed version of Red Hat Linux Enterprise Linux AS Release 2.1 pre-installed and configured for the Real Application Cluster environment based on customized settings supplied by the end user. Customers are advised to purchase a license within the 30 days, either from your hp/Red Hat reseller, Red Hat or hp. | |
| | Oracle Software | Oracle9i Real application Cluster Release 9.2 Software and Licenses Pre installed Oracle9i Real Application Cluster software, test database and a 30-day software license. Customers are advised to purchase a license within the 30 days, either from your Oracle reseller, or Oracle. The software itself is not affected by the subsequent purchase of the license- that is, no re-installation or changes are necessary to the cluster. However, the software license is required to access support for Oracle software | |
| Services | | | |
| 1 | EVA Service | For EVA service please contact HP (800-444-7575) | |
| 1 | H9147A | Oracle 9i RAC Express Service | |