

HP/NHP SATA 3.5" Hard Drive Compatibility Table

		Systems																																						
		ProLiant ML350 G5	ProLiant ML350 G4P	ProLiant ML310 G5	ProLiant ML310 G4	ProLiant ML310 G3	ProLiant ML310 G2	ProLiant ML150 G5	ProLiant ML150 G3	ProLiant ML150 G2	ProLiant ML115 G5	ProLiant ML115 G3	ProLiant ML110 G5	ProLiant ML110 G4	ProLiant ML110 G2/G3	ProLiant DL385 G5P	ProLiant DL380 G4P	ProLiant DL380 G4	ProLiant DL320 G5P	ProLiant DL320 G4/G5	ProLiant DL320 G3	ProLiant DL320s	ProLiant DL185 G5	ProLiant DL180 G5	ProLiant DL180 G1 (APJ only)	ProLiant DL165 G5	ProLiant DL160 G5P	ProLiant DL160 G5	ProLiant DL145 G3	ProLiant DL145 G2	ProLiant DL140 G3	ProLiant DL140 G2	ProLiant DL120 G5	StorageWorks MSA60	StorageWorks MSA20					
Capacity (GB unless otherwise noted)																																								
Option Kits (Spare Kit)		Internal Drive Models																								Supported Drive Models														
Previous Generation																																								
383410-B21+ (399967-001)	80						X					X		X	X																							6L080M0, ST3808110AS, FB080C4080, WD800AAJS-70TDA1		
411275-B21+ (399968-001)	160						X	X			X	X	X	X	X								X				X	X	X	X	X	X	X	X	X			6L160M0, ST3160812AS, FB160C4081, WD1600JS-70SGB1, GB0160CAARV		
411276-B21+ (399969-001)	250						X	X			X	X	X	X	X							X				X	X	X	X	X	X	X	X	X	X			7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250CB045		
*404469-B21+ (404654-001) (404654-002)	500						X	X			X	X	X	X	X							X				X	X	X	X	X	X	X	X	X	X			6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1		
349237-B21 (397551-001)	80	X	X	X	X	X	X		X	X							X	X	X	X	X	X	X	X	X	X	X	X	X									6L080M0, ST3808110AS, FB080C4080, WD800AAJS-70TDA1		
349238-B21 (397552-001)	160	X	X	X	X	X	X	X	X	X							X	X	X	X	X	X	X	X	X	X	X	X	X	X									6L160M0, ST3160812AS, FB160C4081, WD1600JS-70SGB1, GB0160CAARV	
349239-B21 (397553-001)	250	X	1, 2	X	X	2	X	X	X	X							X	X	X	X	X	X	X	X	X	X	X	X	X	X					X	X			7L250S0, 6L250S0, ST3250624AS, ST3250620NS, WD2500YS-70SHB1, GB0250CB045	
395473-B21 (395501-001) (395501-002)	500	X	1, 2	X	X	2	X	X	X	X							X	X	X	X	X	X	X	X	X	X	X	X	X	X					X	X			6H500F0, ST3500641AS, ST3500630NS, GB0500C4413, WD5000YS-70VJB1	
432341-B21 (432401-001) (432401-002)	750	X	1, 2	X	X	2	X	X								X		X	X				X	X	X	X	X	X	X	X					X	X			ST3750640NS, GB0750C4414, BF0750C8047	
Current Generation																																								
458947-B21+ (483096-001) 3.0Gb	160						X				X	X	X	X													X	X	3	X		X		X			GB0160EAFJE, GB0160EAEZH			
458939-B21+ (459315-001) 3.0Gb	250						X				X	X	X	X													X	X	3	X		X		X			GB0250EAFJF			
458941-B21+ (459316-001) 3.0Gb	500						X				X	X	X	X													X	X	3	X		X		X			GB0500EAFJH			
462595-B21+ (462618-001) 3.0Gb	750						X				X	X	X	X													X	X	3	X		X		X			GB0750EAFJK			
458945-B21 (483095-001) 3.0Gb	160	X	X	3	3		X	3							X						3	3	X	X	3	3	X	X	3	X		X					GB0160EAFJE, GB0160EAEZH			
458926-B21 (459318-001) 3.0Gb	250	X	1, 2	3	3		X	3						X								3	3	X	X	3	3	X	X	3	X		X			X	X	GB0250EAFJF		
458928-B21 (459319-001) 3.0Gb	500	X	1, 2	3	3		X	3						X									3	3	X	X	3	3	X	X	3	X		X			X	X	GB0500EAFJH	
458930-B21 (459320-001) 3.0Gb	750	X	1, 2	3	3		X	3						X												X	X	3	3	X	X	3	X		X			X	X	GB0750EAFJK
454146-B21 (454273-001) 3.0Gb	1 TB	X	1, 2	3	3		X	3						X												X	X	3	3	X	X	3	X		X			X	X	GB1000EAFJL

Contain 7200 RPM drives
 + Denotes Non Hot Plug
 * Denotes FIO only

* Compatibility Notes:
 Blank= Not Supported
 X= Supported

1= To ensure optimum thermal conditions, the server should be running with the 8-19-05 system ROM or later.
 2= When running 3 or more drives in this server, it is recommended that the system configuration be set for 100% fan speed.
 3= A minimum version of System ROM is required to support this SATA drive on this server when configured with an embedded SATA or embedded SATA RAID controllers.
 Transfer rates of SATA drives are dependant on the controller and HBA transfer rate. Please see Quickspecs for product specifications.

© Copyright 2004-2008 Hewlett-Packard Development Company, L.P.
 The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.