

hp StorageWorks

fabric manager version 3.0.x release notes

Part Number: AV-RTT5A-TE

First Edition (October 2002)

Product Version: V3.0.x

This document contains last-minute and supplemental information about your Fabric Manager software. In the event of conflicting information between these Release Notes and other documents contained in this product release, the Release Notes contents take precedence. For the latest version of these Release Notes and other product documentation, visit the StorageWorks website at:

<http://www.compaq.com/storage/index.html>.



i n v e n t

© Hewlett-Packard Company, 2002. All rights reserved.

Hewlett-Packard Company makes no warranty of any kind with regard to this material, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

This document contains proprietary information, which is protected by copyright. No part of this document may be photocopied, reproduced, or translated into another language without the prior written consent of Hewlett-Packard. The information contained in this document is subject to change without notice.

HP, Compaq, and StorageWorks are trademarks of Hewlett-Packard Company in the U.S. and/or other countries.

BROCADE, the Brocade B weave logo, Brocade: the Intelligent Platform for Networking Storage, SilkWorm, and SilkWorm Express, are trademarks or registered trademarks of Brocade Communications Systems, Inc. or its subsidiaries in the United States and/or in other countries.

All other product names mentioned herein may be trademarks of their respective companies.

Confidential computer software. Valid license from Compaq required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Hewlett-Packard Company shall not be liable for technical or editorial errors or omissions contained herein. The information is provided "as is" without warranty of any kind and is subject to change without notice. The warranties for Hewlett-Packard Company products are set forth in the express limited warranty statements accompanying such products. Nothing herein should be construed as constituting an additional warranty.

Printed in the U.S.A.

Fabric Manager Version 3.0.x Release Notes
First Edition (October 2002)
Part Number: AV-RTT5A-TE

Release Notes Contents

These Release Notes cover the following major Fabric Manager topics:

- “Fabric Manager Overview,” page 4
- “Limitations,” page 4
- “Known Issues,” page 4

Intended Audience

This document is intended for customers who purchased HP StorageWorks SAN or HP StorageWorks Core switches.

Related Documentation

For the most current information about the HP StorageWorks products, visit the support Web site located at visit the StorageWorks website at: <http://www.compaq.com/storage/index.html>. For information about product availability, configuration, and connectivity, consult your HP account representative.

For additional information on Fabric Manager, refer to *HP StorageWorks Fabric Manager Version 3.0 User Guide*, part number AA-RTSKA-TE.

Fabric Manager Overview

Fabric Manager provides a graphical interface that allows the administrator to monitor and manage an entire fabric from a standard workstation. Fabric Manager can be used to manage fabrics containing integrated fabrics, in addition to individual switches.

Fabric Manager provides high-level information about all switches in the fabric, launching the Web Tools application when more detailed information is required. The launching of Web Tools is transparent, providing a seamless user interface. In addition to the ability to view the switches as a group, Fabric Manager provides improved efficiencies in the management of SANs over Web Tools alone.

Limitations

None

Known Issues

None